

CT 1040 DATA SETTING

Counting sensor and UV sensor adjustment: 1、Press ADD until display change.

2、Insert white paper, press “BATCH” key.

3、display show F00 F00 succeed ,display show E00 failed ,try again..

Setting the Data: 1、Press “BATCH” 5 seconds,

2、press “+” key add 1, press “—” reduce 1。

Data	Default	Description	Scale	Notes
0—YN	00	Counting Polymer money	0-1	0 colse / 1 open
1— A	05	UV sensor	1—10	More higher more Alive
2—1b	02	MG1	1—10	More higher more Alive
3—2b	03	MG2	1—10	More higher more Alive
4—3b	04	MG3	1—10	More higher more Alive
5—SC	05	Brake	1—10	More higher more Alive
6—qd	05	Start sensor	1—10	More higher more Alive
7—qL	05	Clear sensor	1—10	More higher more Alive
A—Uo	01	Fake money add number	0-1	0 not add / 1 add
B—FB	05	SIZE	1—10	More higher less Alive
C—C2	05	Double-note	1—10	More higher more Alive
D—B2	00	Half-note add number	0-1	0 not add / 1 add

3、press “RESET” key save data.

4.return to default: press ”BATCH” key , Set to102 pcs, press “BATCH” key back to default。